

AcousticFab, LLC

Repair Station Part Number Capability list

FAR-125: AUJR406x & EASA 145.6116

4/26/2012

Uncontrolled Copy, Reference Only

Customer P/N	Nomenclature	APU	Aircraft	Notes/Comments
4503825	Exhaust liner	APS 500	ERJ 135/145	Repairs sold exclusively through Hamilton Sundstrand
4503847	Inlet Silencer	APS 500	ERJ 135/145	Repairs sold exclusively through Hamilton Sundstrand
4501423	Air Inlet Duct	APS 500	ERJ 135/145	Repairs sold exclusively through Hamilton Sundstrand
4501424	Air Inlet Duct	APS 500	ERJ 135/145	Repairs sold exclusively through Hamilton Sundstrand
4502421	Air Inlet Duct	APS 500	ERJ 135/145	Repairs sold exclusively through Hamilton Sundstrand
4503801C	Exhaust Assembly	APS 500	ERJ 135/145	Repairs sold exclusively through Hamilton Sundstrand
4504716	Plenum Duct	APS 500	ERJ 135/145	Repairs sold exclusively through Hamilton Sundstrand
4951952	Exhaust liner	APS2300	ERJ 170/190	Repairs sold exclusively through Hamilton Sundstrand
4952614	Eductor	APS2300	ERJ 170/190	Repairs sold exclusively through Hamilton Sundstrand
4952615	Exhaust liner	APS2300	ERJ 170/190	Repairs sold exclusively through Hamilton Sundstrand
4952354	Inlet Silencer	APS2300	ERJ 170/190	Repairs sold exclusively through Hamilton Sundstrand
4951881	Plenum	APS2300	ERJ 170/190	Repairs sold exclusively through Hamilton Sundstrand
4503098	Air Inlet Duct	APS 1000	Q-400	Repairs sold exclusively through Hamilton Sundstrand
4501694	Fan Duct Assy	APS 1000	Q-400	Repairs sold exclusively through Hamilton Sundstrand
4502599	Duct Inlet	APS 1000	Q-400	Repairs sold exclusively through Hamilton Sundstrand
4502600	Duct Inlet	APS 1000	Q-400	Repairs sold exclusively through Hamilton Sundstrand
400-51100-1	Inlet Silencer	APS 1000	Q-400	
400-51300-1	Exhaust Silencer Assy	APS 1000	Q-400	
400-51302-1	Exhaust Liner	APS 1000	Q-400	
4500357B	Exh Attenuator	APS 2000	B 737	Repairs sold exclusively through Hamilton Sundstrand
4500305	Exh Attenuator	APS 2000	B 737	Repairs sold exclusively through Hamilton Sundstrand
335707650	Exh Attenuator	APS 2000	B 737	Repairs sold exclusively through Hamilton Sundstrand
335707960	Exh Attenuator	APS 2000	B 737	Repairs sold exclusively through Hamilton Sundstrand
335707810	Exh Attenuator	APS 2000	B 737	Repairs sold exclusively through Hamilton Sundstrand
335708120	Inlet Attn	APS 2000	B 737	Repairs sold exclusively through Hamilton Sundstrand
335708270	Inlet Attn	APS 2000	B 737	Repairs sold exclusively through Hamilton Sundstrand
170211-101	Inlet Attn	APS 2000	B 737	Repairs sold exclusively through Hamilton Sundstrand
335707410	Inlet Attn	APS 2000	B 737	Repairs sold exclusively through Hamilton Sundstrand
4500590	Duct Assy	APS 2000	B 737	Repairs sold exclusively through Hamilton Sundstrand